

1. DUE TO THE FINDING OF A BUCKING BAR (USED IN RIVETTING) IN THE WRECKAGE OF F-101, 286, THE ACCIDENT BOARD HAS NOT COMPLETED THEIR INVESTIGATION.

25X1A 25X1A

25X1A

25X1A

25X1A

- 2. UNLESS EVIDENCE IS FOUND TO INDICATE THIS BAR
 CAUSED MALFUNCTIONS IN STABILATOR OR OTHER CONTROL
 SYSTEMS THE PRIMAPY BOARD FINDING WILL BE PILOT ERROR.
- 3. THERE IS NO INTENTIONS OF BOARD TO INDICATE ANY SUPERVISORY ERROR WHATSOEVER, HOWEVER, THEY ARE RECOMMENDING A CHASE SOP REVISION TO SPECIFICALLY ELIMINATE CHASE DURING DARKNESS EXCEPT IN EMERGENCY.
- 4. FINAL BOAPD ACTION AND REPORT ESTIMATED TO BE COMPLETED BY 5 OCT 1700Z.

SECRET
Approved For Release 2000/05/05 : CIA-RDP71B00590R0002001000 15-8

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

Approved For Release 2009/05/05 : CIA-RDP71B00590R000200100015-8

IN 55598

25X1A

9936)

SECRET

PAGE 2

5. WE HAVE ELIMINATED ALL CHASE FLYING EXCEPT IN EMERGENCY OR WHEN REQUESTED BY ARTICLE PILOT. HAVE EITHER GROUND OR AIRBORNE F-101 ALERT FOR THIS CONTINGENCY.

SECRET TOP: 050047Z OCT 67